

REPORT OF TRAFFIC ACCIDENT INVOLVING AN AUTONOMOUS VEHICLE

DMV	USE	ONL	Υ	
AVT NUMBER	,			
NAME				
17,000				

Instructions: Please print within the spaces and boxes on this form. If you need to provide additional information on a separate piece of paper(s) or you include a copy of any law enforcement agency report, please check the box to indicate "Additional Information Attached."

- Write unk (for unknown) or none in any space or box when you do not have the information on the other party involved.
- Give insurance information that is complete and which correctly and *fully* identifies the **company** that issued the insurance policy or surety bond, or whether there is a certificate of self-insurance.
- Place the National Association of Insurance Commissioners (NAIC) number for your Insurance or Surety Company in the boxes provided. The NAIC number should be located on the proof of insurance provided by you company or you can contact your insurer for that information.
- Identify any person involved in the accident (driver, passenger, bicyclist, pedestrian, etc) that you saw was injured or complained of bodily injury or know to be deceased.
- Record in the PROPERTY DAMAGE line any damage to telephone poles, fences, street signs, guard post, trees, livestock, dogs, buildings, parked vehicles, etc., including a description of the damage.
- Once you have completed this report, please mail to: Department of Motor Vehicles, Occupational Licensing Branch, P.O. Box 932342, MS: L224, Sacramento, CA 94232-3420

SECTION 1 — MAN	IUFACTURER'S INFORMATION				
MANUFACTURER'S NAME			AVT NUMBER		
GOOGLE AUTO LLO	g		A T NOWBER		
BUSINESS NAME			TELEPHONE NUMBER		
GOOGLE AUTO LLO	g		(680 3083 0000		
STREET ADDRESS	СПУ		STATE ZIP CODE		
			CA 94043		
SECTION 2 — ACC	IDENT INFORMATION				
DATE OF ACCIDENT	TIME OF ACCIDENT VEHICL	EYEAR MAKE	TMODEL		
12/11/2017	11:36 ☑ AM ☐ PM 2012		RX 450H		
LICENSE PLATE NUMBER	VEHICLE IDENTIFICATION NUMBER		STATE VEHICLE IS REGISTERED I		
	TJBC1BA3C2432177		£2A		
ADDRESS/LOCATION OF ACCIDE	ENT CITY	COUNTY	STATE ZIP CODE		
EL CAMINO REAL A	AND RENGSTORFF MOU	JNTAIN VIEW SANTA CLARA	CA 94040		
Vehicle ☑ Mo	ving Involved in	☐ Pedestrian	NUMBER OF VEHICLES INVOLVED		
	pped in Traffic the Accident:		2		
DRIVER'S FULL NAME (FIRST, MI	DDLE, LAST)	DRIVER LICENSE NUMBER	STATE DATE OF BIRTH		
		D5361362	CA 377/28/1990 A		
NSURANCE COMPANY NAME O	R SURETY COMPANY AT TIME OF ACCIDENT	POLICY NUMBER			
		MWTB307725			
COMPANY NAIC NUMBER		POLICY PERIOD			
		FROM TO	06/01/2017		
SECTION 3 — OTH	ER PARTY'S INFORMATION				
VEHICLE YEAR	MODEL				
1997	TOYOTA COROLLA				
LICENSE PLATE NUMBER VEHICLE IDENTIFICATION NUMBER			STATE VEHICLE IS REGISTERED I		
			CA		
Vehicle ☑ Mo	ving Involved in	☐ Pedestrian	NUMBER OF VEHICLES INVOLVED		
	pped in Traffic the Accident:		2		
DRIVER'S FULL NAME (FIRST, MI		DRIVER LICENSE NUMBER	STATE DATE OF BIRTH		
	RIK	D\$834570	CA 62/18/1937		
INSURANCE COMPANY NAME OR SURETY COMPANY AT TIME OF ACCIDENT		POLICY NUMBER			
ALLSTATE		NMS4715175			
COMPANY NAIC NUMBER		POLICY PERIOD •			
		TOPE TOPE TOPE TO SEE			

☐ Additional information attached.

	RTY DAMAGE				
NAME (FIRST, MIDDLE, LAST)					-
ADDRESS	СІТҮ			STATE	ZIP CODE
CHECK ALL THAT APPLY Injured	☐ Deceased	☐ Driver	☐ Passenger	☐ Bicyclist	☐ Property
NAME (FIRST, MIDDLE, LAST)		A Management			V
ADDRESS	CITY			STATE	ZIP CODE
CHECK ALL THAT APPLY Injured	☐ Deceased	☐ Driver	☐ Passenger	☐ Bicyclist	☐ Property
PROPERTY DAMAGE					
PROPERTY OWNER'S NAME				TELEPHON	NE NUMBER
STREET ADDRESS	CITY			STATE	ZIP CODE
WITNESS NAME				TELEPHON	NE NUMBER
STREET ADDRESS	CITY			STATE	ZIP CODE
WITNESS NAME				TELEPHON	E NUMBER
STREET ADDRESS	CITY			STATE	ZIP CODE
☐ Additional information attached.	·			RAMARAKAN MURANGAN ANDARA MARANA	
SECTION 5 — ACCIDENT DETAILS - DI Autonomous Mode Conventiona A Google Lexus autonomous vehicle ("Google"	al Mode	uthwest in auto	nomous mode on Re	ngstorff Ave. in N	Jountain View was
Autonomous Mode Conventional A Google Lexus autonomous vehicle ("Google involved in an accident. As the Google AV mainside left turn lane also turning left onto El C Google AV. The Google AV test driver immebrought it to a stop at the side of El Camino R damage to its front bumper. The Google AV w	al Mode e AV") traveling sot ade a left turn onto I amino Real crossed diately disengaged t eal. The Google AV vas traveling approx	El Camino Real into the outsido he autonomous sustained dam imately 20 mpl	from the outside left eleft turn lane and contechnology, took manage to its driver-side and the other vehicle	t turn lane, another ollided with the data anual control of the doors. The other	er vehicle in the river's side of the ne vehicle and vehicle sustained
Autonomous Mode Conventional A Google Lexus autonomous vehicle ("Google involved in an accident. As the Google AV mainside left turn lane also turning left onto El C Google AV. The Google AV test driver immediate brought it to a stop at the side of El Camino R damage to its front bumper. The Google AV with matching the time of the collision. There were not the time of the collision at the time of the collision.	al Mode e AV") traveling sot ade a left turn onto I amino Real crossed diately disengaged t eal. The Google AV vas traveling approx	El Camino Real into the outsido he autonomous sustained dam imately 20 mpl	from the outside left eleft turn lane and contechnology, took manage to its driver-side and the other vehicle	t turn lane, another ollided with the data anual control of the doors. The other	er vehicle in the river's side of the ne vehicle and vehicle sustained
Autonomous Mode Conventional A Google Lexus autonomous vehicle ("Google involved in an accident. As the Google AV mainside left turn lane also turning left onto El C Google AV. The Google AV test driver immerbrought it to a stop at the side of El Camino R damage to its front bumper. The Google AV may may be at the time of the collision. There were not the time of the collision at the time of the collision.	al Mode e AV") traveling sot ade a left turn onto I amino Real crossed diately disengaged t eal. The Google AV vas traveling approx	El Camino Real into the outsido he autonomous sustained dam imately 20 mpl	from the outside left eleft turn lane and contechnology, took manage to its driver-side and the other vehicle	t turn lane, another ollided with the data anual control of the doors. The other	er vehicle in the river's side of the ne vehicle and vehicle sustained
Autonomous Mode	al Mode e AV") traveling son ade a left turn onto I amino Real crossed diately disengaged t eal. The Google AV vas traveling approx o injuries reported at	El Camino Real into the outside he autonomous sustained dam imately 20 mpl the scene by e	from the outside left turn lane and contechnology, took mage to its driver-side and the other vehicuither party.	t turn lane, anothe ollided with the da anual control of the doors. The other le was traveling a	er vehicle in the iver's side of the le vehicle and vehicle sustained pproximately 15
Autonomous Mode	al Mode e AV") traveling son ade a left turn onto I amino Real crossed diately disengaged t eal. The Google AV vas traveling approx o injuries reported at	El Camino Real into the outside he autonomous sustained dam imately 20 mpl the scene by e	from the outside left turn lane and contechnology, took mage to its driver-side and the other vehicuither party.	t turn lane, anothe ollided with the da anual control of the doors. The other le was traveling a	er vehicle in the iver's side of the le vehicle and vehicle sustained pproximately 15
Autonomous Mode Conventional A Google Lexus autonomous vehicle ("Google involved in an accident. As the Google AV mainside left turn lane also turning left onto El C Google AV. The Google AV test driver immerbrought it to a stop at the side of El Camino R damage to its front bumper. The Google AV with might at the time of the collision. There were not make the collision of the collision of the collision of the collision of the collision. The correct. If turther certify that I am the authorized in the collision of the collision of the correct.	al Mode e AV") traveling son ade a left turn onto I amino Real crossed diately disengaged t eal. The Google AV vas traveling approx o injuries reported at	El Camino Real into the outside he autonomous sustained dam imately 20 mpl the scene by e	from the outside left turn lane and contechnology, took mage to its driver-side and the other vehiclither party.	it turn lane, anothe ollided with the danual control of the doors. The other le was traveling a late that the foremed employer.	er vehicle in the iver's side of the le vehicle and vehicle sustained pproximately 15
Autonomous Mode Conventional A Google Lexus autonomous vehicle ("Google involved in an accident. As the Google AV mainside left turn lane also turning left onto El C Google AV. The Google AV test driver immerbrought it to a stop at the side of El Camino R damage to its front bumper. The Google AV with might at the time of the collision. There were not make the side of El Camino R damage to its front bumper. The Google AV with might at the time of the collision. There were not make the side of El Camino R damage to its front bumper. The Google AV with might at the time of the collision. There were not make the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The Google AV with a stop at the side of El Camino R damage to its front bumper. The	al Mode e AV") traveling son ade a left turn onto I amino Real crossed diately disengaged t eal. The Google AV vas traveling approx o injuries reported at	El Camino Real into the outside he autonomous sustained dam imately 20 mpl the scene by e	from the outside left turn lane and contechnology, took mage to its driver-side and the other vehiclither party.	it turn lane, anothe ollided with the danual control of the doors. The other le was traveling a late that the foremed employer.	er vehicle in the iver's side of the le vehicle and vehicle sustained pproximately 15
	al Mode e AV") traveling son ade a left turn onto I amino Real crossed diately disengaged t eal. The Google AV vas traveling approx o injuries reported at	El Camino Real into the outside he autonomous sustained dam imately 20 mpl the scene by e	from the outside left turn lane and contechnology, took mage to its driver-side and the other vehiclither party.	it turn lane, anothe ollided with the danual control of the doors. The other le was traveling a late that the foremed employer.	er vehicle in the iver's side of the le vehicle and vehicle sustained pproximately 15